

To All Customers

Rep No. B18066

January 15, 2019

Fuji Electric FA Components &  
Systems Co., Ltd.

---

Timer Socket TP48X (For Timer MS4S Series and MB4 Instantaneous Stop Restart Relays)  
Notification regarding Some Appearance and Shape Changes

---

We would like to thank you for your continued patronage of Fuji products.

We will be changing some products as described below.

Please review the following information and take appropriate actions.

Please also inform all related sections of your company of these changes.

Product name	Timer socket
Series name	Timer MS4S Series, MB4 Instantaneous Stop Restart Relays
Type	TP48X
Changed parts	Top and bottom surfaces of socket
Details of the change	(1) Removal of old symbol mark from the top surface of the socket (2) Change of shape around the rail mounting on the bottom surface of the socket *Refer to the attachment for more details.
Reason for change	The old symbol mark is being removed following the revision of the plastic molding die, and the shape is being changed to improve moldability.
Date of the production change	Scheduled for products to be produced from June 2019
Attachment	"Comparison of Socket Appearances and Shapes"
Notes concerning the changes	This change will not affect product performance.

Attachment: Comparison of Socket Appearances and Shapes  
 Timer Socket TP48X (For Timer MS4S Series and Instantaneous Stop Restart Relays)  
 Change in Some Appearances and Shapes



Rep No.B18066

January 15, 2019

Fuji Electric FA Components &  
 Systems Co., Ltd.

[Details of the change]

- (1) Removal of old symbol mark from the top surface of the socket
- (2) Change of shape around the rail mounting on the bottom surface of the socket

